Araknis 520 Router Firmware Release Notes

Version 1.0.4

Release date: 23-10-17

Bug fix

- This firmware release resolves a bug that could cause the router to fail in correctly auto-negotiating the link speed of the SFP port during the boot process, resulting in port shutdown.

Version 1.0.3

- This is the initial release.

Technical Support

For chat and telephone, visit **snp1.co/techsupport** • Email:
TechSupport@SnapOne.com. Visit **snp1.co/tc** for discussions, instructional videos,
news, and more.

Warranty and Legal Notices

Find details of the product's Limited Warranty and other resources such as regulatory
notices and patent and safety information, at **snapone.com/legal** or request a paper
copy from Customer Service at **866.424.4489**.

231017

x20-RT-A