Firmware Release Notes

Araknis Wireless Access Points
Version 1.1.10

Release Details

Release Date	5/26/16
Firmware Version	1.1.10
Product SKUs Affected	AN-500-AP-I-AC
	AN-700-AP-I-AC

New Features
- Changed the system log to only log messages more urgent then level 4(error).

Resolved Functional/Local Issues
- Fixed issue with the traffic shaping limits on respective WAP SKUs. Now in line with what the WAP is actually capable of doing.

- Fixed issue where if VLANs are established per SSID, then traffic shaping rules aren't properly applied.

- Fixed issue where clicking on WPS in the left navigation bar created a configuration change.

- Fixed issue where the file window for upload configuration on the file management page will not close on the Edge browser.

- Fixed issue where clients connected to the guest network always show in the client list as offline, even when they are online.

Resolved Cloud Issues
- Fixed issue where the client list found in OvrC would not report 2.4 GHz clients when band steering was enabled on the access point.

- Fixed issue with properly displaying VLAN ID and configuration options on OvrC. Now displays properly.

Known Cloud Issues
- If you are configuring an SSID in the OvrC app, when using certain special characters, particularly "$", passwords may be truncated. We suggest avoiding the use of special characters in SSID passwords when using OvrC for setup until we resolve this issue in a future release.

Contacting Technical Support
Phone: (866) 838-5052

Email: support@araknisnetworks.com