# Release Notes: Luma Utility

The Luma Utility locates and aids in the setup of Luma recorders and Luma IP cameras. These release notes provide detailed information regarding fixes, enhancements, and/or known issues related to the Luma Utility.

## V3.0.0.51 build 20160908_054

Priority: **Recommended**

Released: 2016/10/27

This firmware adds several key enhancements.

### Enhancements

1. Updated user interface.
2. The RTSP port can now be viewed and edited for each device.
3. Support for password recovery on Luma IP cameras.

### Issues Resolved

*—None—*

### Known Issues

1. When running an older version of NVR firmware (v3.1.2 build 151224 or older), the user is unable to save the DHCP networking setting. The user must log into the NVR web interface to change from DHCP to static or vice versa. With updated NVR firmware, this is not an issue.
2. The number of devices change when the list is refreshed using the “Refresh” button. The user will need to hit the “Refresh” button one or more times to list the correct number of surveillance devices