Release Notes: Luma Wi-Fi / PoE-Enabled Camera Firmware

V5.4.1 build 180731

Priority: **RECOMMENDED**

Released: 2019/04/02

Models Affected

- LUM-300-CUB-IPW-WH

Issues Resolved

1. Improved audio performance through web UI and mobile app.
2. Various other bug fixes.

Known Issues

1. To listen to audio on the mobile app, the stream quality must be set to HIGH.

V5.4.1 build 180424

Priority: **RECOMMENDED**

Released: 2018/06/28

Models Affected

- LUM-300-CUB-IPW-WH

Issues Resolved

1. The unsupported 2-way audio can no longer be enabled via Luma mobile app.
2. Fixed the incorrect SDDP information when connecting camera using Wi-Fi.

Known Issues

1. Wireless part of camera is not connecting to OvrC servers (must use LAN MAC address to connect).
2. OvrC showing the Wi-Fi camera twice.
3. Dynamic Analysis for Motion enabled by default.

V5.4.1 build 180105

Priority: **INSTALLED**

Released: 2018/04/18

This is the release firmware.

Models Affected

- LUM-300-CUB-IPW-WH

Known Issues

1. 2-way audio, while not supported, can be enabled via Luma mobile app.
2. Incorrect SDDP information when connecting camera using Wi-Fi