Purpose

These release notes provide detailed information regarding fixes, enhancements, and known issues related to the Wirepath IP Camera firmware. The firmware versions and their assigned IP cameras are:

1. Wirepath IP Camera version **1.0.20.17**. The following SKUs require this version of firmware:
    *   WPS-300-BUL-IP-GR
    *   WPS-300-BUL-IP-WH
    *   WPS-300-DOM-IP-BL
    *   WPS-300-DOM-IP-WH
    *   WPS-300-CUB-IP-WH
    *   WPS-550-BUL-IP-GR
    *   WPS-550-BUL-IP-WH
    *   WPS-550-DOM-IP-BL
    *   WPS-550-DOM-IP-WH
    *   WPS-750-DOM-IPH-BL
    *   WPS-750-DOM-IPH-WH
    *   WPS-750-BUL-IPH-GR
    *   WPS-750-BUL-IPH-WH

2. Wirepath IP Camera version **1.0.30.31**. The following SKUs require this version of firmware:
    *   WPS-500-PTZ-IP-WH
    *   WPS-750-BUL-IP-GR
    *   WPS-750-BUL-IP-WH
    *   WPS-750-DOM-IP-BL
    *   WPS-750-DOM-IP-WH

New Features/Fixes

Both firmware versions mentioned above have the following fixes:

1. The cameras are now OvrC enabled.
2. Continuous and motion events record when up to three devices (NVRs and/or control systems) access an IP camera using the same login credentials. If a fourth device accesses the same IP camera, the first device loses access to make room for the new device.

Known Issues

Due to the fixes required to address the above issues, **all settings and configurations are set to factory default values** after upgrading to these versions of firmware. Config files from a previous version are not compatible with these latest versions of firmware. We recommend you write down or take screenshots of your configurations before updating your firmware.