

## EA-AMP-HYB-2D-X000 HYBRID AMPLIFIER

### CONTACTING TECH SUPPORT

Phone: (866) 838-5052 (704) 909-5229

Email: TechSupport@SnapOne.com

### FIRMWARE RELEASE 12/02/2021

Model	Main Firmware
EA-AMP-HYB-2D-1000	8.00 -> 8.04
EA-AMP-HYB-2D-2000	5.00 -> 5.03

**important:** This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

### CHANGES IN THIS RELEASE

Enhances reliability with general bug fixes.

### FIRMWARE RELEASE 04/13/2021

Model	Main Firmware
EA-AMP-HYB-2D-1000	8.00 -> 8.03
EA-AMP-HYB-2D-2000	5.00 -> 5.03

**important:** This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

### CHANGES IN THIS RELEASE

#### Improvements

1. Added webconnect from OvrC.
2. Added front panel lockout to prevent customer changes to amplifier settings
3. FW upgrade process has been optimized so future updates share one firmware file for both the 1000 and 2000 models
4. Fixed SDDP flooding issue which caused amplifier and network slowdowns
5. Future MAC OS firmware upgrade issues resolved
6. Control system (telnet) password now syncs with web UI password

### FIRMWARE RELEASE 09/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	6.12
EA-AMP-HYB-2D-2000	3.12

### CHANGES IN THIS RELEASE

#### Improvements

1. Updated user accounts and user access to meet California's new IoT security legislation.
2. Updated volume ramping curve for improved performance for units connected to a C4 system.
3. Resolved an OvrC drop off issue, the amp would disconnect then would not automatically reconnect.

## FIRMWARE RELEASE 09/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	5.10

### CHANGES IN THIS RELEASE

#### Improvements

1. Added Save/Load Preset Feature
2. Added Web UI firmware update Feature
3. Made UI color optimizations
4. Fixed iOS repeat logout issue
5. Fixed wrong password entry/lock out issue

## FIRMWARE RELEASE 05/20/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	4.02

### CHANGES IN THIS RELEASE

#### Improvements

1. Speaker profile Y-Ch1 changed to Mono CH1 + Ch2
2. Fixed issue where 12V trigger unable to power down during "light" power mode
3. Extended digital certificates validity date

## FIRMWARE RELEASE 04/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	3.00

### CHANGES IN THIS RELEASE

#### Improvements

1. This is release firmware