
Release Details

- Version: WB10.5930
- Release Date: 10/26/15
- Products Affected: WB-300-IP-3, WB-300VB-IP-5, WB-700CH-IPV-12

Improvements

SnapAV identified these issues after launch of the WB-300-IP-3 through rigorous stress-testing of the units. Firmware revision also includes support for future WattBox IP models WB-300VB-IP-5, and WB-700CH-IPV-12.

- Resolves an issue where messages between the WattBox and OvrC were sent in the incorrect order, resulting in potential false outlet status being represented.
- Resolves an issue during an infinite reboot where outlet status would get out of sync after ~24 hours.
- Resolves an issue where the “Auto Reboot” slider would briefly show false status moments after being pressed on OvrC mobile.

Contacting Technical Support

- Phone: 866.838.5052
- Email: techsupport@wattboxpower.com