

Release Notes: Luma Fisheye Camera Firmware

V5.4.5 build 180209

Priority: **IMPORTANT**

Released: 2018/06/14

This fixes several issues and adds control system support.

Models Affected

- LUM-500-FISH-IP-WH

Enhancements

1. Support for MJPEG stream from PTZ channels.
2. Cameras connected via virtual host no longer unexpectedly exit the interface on a Windows PC.

Issues Resolved

1. The unsupported SNMP menu has been removed from the web UI.
2. Control System support for: Control4, Crestron, Elan g!, RTI and URC.
3. Take a PTZ channel snapshot using CGI commands.

Known Issues

1. Camera connected via virtual host may unexpectedly exit the web UI on Safari.

V5.4.5 build 171201

Priority: **IMPORTANT**

Released: 2018/02/21

This is the release firmware.

Models Affected

- LUM-500-FISH-IP-WH

Known Issues

1. Camera connected via virtual host may unexpectedly exit the web UI on Safari.
2. No support for control systems.
3. All snapshots are of the circular fisheye camera view only.