

USING THE ART CLEANBoxPro WITH THE CROWN AMPLIFIER FOR EPISODE LANDSCAPE

1. Connect your Un-balanced source to the RCA input (CH1 & CH2) of the CLEANBoxPro.




Un-balanced Ports

2. Connect XLR (female end) to Balanced output (CH1 & CH2) to the CLEANBoxPro.




CLEANBoxPro


3. If the XLR cable has the male connector on the other end, cut-off to expose the positive, negative, and ground conductors.
4. Terminate the conductors, for both CH1 & CH2, to either the spare Phoenix connectors of the Crown amp or repurpose the phoenix connectors from the summing cable, according to the following sequence.



5. Connect a jumper from CH1 phoenix connector to CH2 phoenix connector for each terminal according to the following.



6. Connect each phoenix connector to the appropriate channel on the Crown Amplifier (be mindful that the channels are in different physical sequence on the rear of the Crown, as compared to the sequence of the CLEANBoxPro).



CONTACT TECH SUPPORT

Need Help? Contact Tech Support!

If you need further clarification, please call tech support at 866.838.5052, or email support@snapav.com. For other information, instructional videos, support documentation, or ideas, visit our website and view your item's product page at www.snapav.com.

Phone: (866) 838-5052

Email: Techsupport@SnapAV.com



Rev: 160919-0300