

## Release Notes: Luma 310 DVR Firmware

### V3.5.35 build 191123

Priority: **REQUIRED**

Released: 2019/12/10

#### Models Affected

LUM-310-DVR-4CH-0T

LUM-310-DVR-8CH-0T

LUM-310-DVR-16CH-0T

LUM-310-DVR-4CH-1T

LUM-310-DVR-8CH-1T

LUM-310-DVR-16CH-2T

#### Enhancements

1. None; this firmware fixes the LumaLink connectivity issue.

#### Issues Resolved

1. Fixed LumaLink connectivity issue.