

Release Notes: Luma X10 IP Camera Firmware

V5.5.52 build 181008

Priority: **INSTALLED**

Released: 2019/03/05

Models Affected

- All Luma 110, 310 and 710 series IP cameras

Issues Resolved

1. This is first release firmware

Known Issues

1. LumaLink connection method not supported in the Luma VMS for PC client software at this time.